

H.O. 1300 - AUG 61

ROYAL CANADIAN AIR FORCE

SUBJECT AIRCRAFT
VENTURA

RAF NO: AE661

FOR CROSS REFERENCES SEE INSIDE COVER

REGIMENT NO. 1	GRADE NO. 2	NAME	DATE	INITIALS	STATUS	NO. OF DAYS	NO. OF MILES	STATUS NO. 1	STATUS NO. 2
		LH							

Handwritten notes:
 2-9-43 ME
 16-9-43 48
 14/10/43 SA
 2-9-43 ME
 16-9-43 48
 14/10/43 SA

FILE CLOSED
 DO NOT REMOVE OR DESTROY THIS FILE
 AS IT CONTAINS INFORMATION OF A
 CONFIDENTIAL NATURE.

R. C. A. F. MESSAGE

OFFICE DATE STAMP & SERIAL NO.

APR 1945 SAC WIT 12 5000

FROM	DA DTG	DATE	REFERENCE AND DATE	TITLE
7 JAL	7 JAL	7 JAL		

FILE MADE ON 2

FLYING ACCIDENT SIGNAL REPORT REFERENCE: C.A.P. 100. SECTION 4. PAR 14.

UNIT TO WHICH AIRCRAFT BELONGS: 34 DTU PERMD HELD POINT

PLACE, DATE AND TIME OF ACCIDENT: PERMD HELD POINT 1045

TYPE AND REGISTRATION NUMBER OF ENGINE (S) AND AIRCRAFT INVOLVED: VENTURA 144661 UNIT 400/A150905 STALL

CATEGORY OF CRASH: STALL

F. FULL NAME, RANK AND NUMBER OF PILOT AND WHETHER KILLED, MISSING, DANGEROUSLY, SEVERELY OR SLIGHTLY INJURED, OR UNINJURED. 1ST LT BRIGGS W. W. UNINJURED

G. OTHER OCCUPANTS AND WHETHER KILLED, MISSING, DANGEROUSLY, SEVERELY OR SLIGHTLY INJURED, OR UNINJURED. NONE

H. FULL NAMES, RANKS, NUMBERS AND DUTIES OF OTHER PERSONNEL INVOLVED (NOT OCCUPANTS OF AIRCRAFT) AND WHETHER KILLED, DANGEROUSLY, SEVERELY OR SLIGHTLY INJURED, OR UNINJURED. NONE

J. NAMES, RELATIONSHIPS AND ADDRESSES OF NEXT OF KIN OF PERSONNEL KILLED, MISSING, DANGEROUSLY, SEVERELY INJURED, OR UNINJURED. NONE

L. NATURE OF DUTY OR WORK IN WHICH INVOLVED AT TIME OF ACCIDENT. NONE

M. NATURE AND SHORT DESCRIPTION OF ACCIDENT. STALL AT PERMD HELD POINT

STATUS OF REPORT OF ACCIDENT AT OCCASION OF STATE	STATUS OF REPORT OF ACCIDENT AT OCCASION OF STATE
12	12

NOT COPY TO VENT. DTG

APR 1945

PURPOSE OF FLIGHT:

Training flight.

NATURE OF ACCIDENT:

Port tire blew on takeoff, A/C swung

TECHNICAL OFFICER'S REPORT:

violently and on account of insufficient speed for takeoff, pilot re-
tracted U/C to avoid collision with
A/C taxiing down another runway.

SUMMARY NO.

05/07E

CLASSIFICATION:

~~15. Fire failure on takeoff.~~

16. *Other*

SECONDARY OR CONTRIBUTORY FACTORS:

~~9. Swinging~~

37. *See burst.*

37

ACTION TAKEN:

M11